



# Inspection Report

1234 Main Street  
Torrance, California 90505



PREPARED EXCLUSIVELY FOR:  
John Smith



Monday, July 4, 2022



INSPECTOR:  
Steve Carroll

CREIA Past Chairman of the Board  
Master CREIA Inspector - ASHI Certified Inspector

## **EXECUTIVE SUMMARY**

This first section is a Summary review of the inspector's findings during this inspection. However, it does not contain every detailed observation and condition. This is provided as an additional service to our client, and is designed to provide more detailed description of conditions that may require your immediate attention, and in some cases suggestion for securing further evaluation or resolution.

Summary may include:

~> Items that are no longer functioning as intended

~> Conditions that present safety issues

~> Items or conditions that require repair, replacement, or further evaluation by a specialist

The Full Report (starts after the index) includes the Summary items (in BLUE) as well as:

~> Conditions requiring repair that arise due to wear and the passage of time

~> Conditions that have not significantly affected usability or function, but may if left unattended

The COMPLETE REPORT consists of: Executive Summary, Full Report and Inspection Agreement.

Our recommendations are not intended as criticisms of the building, but as professional opinions regarding conditions present. As a courtesy, the inspector list items that they feel have priority in the Executive Summary. Although the items listed in this section may be of higher priority in the opinion of the inspector, it is ultimately the client's responsibility to review the entire report. If the client has questions regarding any of the items listed, please contact the inspector for further consultation.

Lower priority conditions contained in the body of the report that are disregarded or neglected may become higher priority conditions. Also, do not equate low cost with low priority. Cost should not be the primary motivation for performing repairs. All repair and upgrade recommendations are important and need attention.

#### NOTICE TO THIRD PARTIES:

The inspection report is for the sole benefit and reliance of Client named in the report and is nontransferable. The report is a summary of the inspection and all conditions between Inspector and Client is issued subject to the terms, conditions and limitations under which the inspection was performed. The terms, conditions and limitations are part of this report and are attached hereto and incorporated by referenced herein. Inspector assumes no liability for third party interpretation or use of the report. THIRD PARTIES ARE ENCOURAGED TO OBTAIN A HOME INSPECTION FROM A QUALIFIED INSPECTOR OF THEIR CHOICE.

Throughout the Executive Summary and Full Report, you'll find special symbols at the front of certain comments. Below are the symbols and their meanings:

**FE SC** = Conditions in their present state may pose a hazard to humans, the structure or both. = Conditions that warrant further evaluation by a qualified specialist, disclosure from the sellers, or future observations.

**CR** = Conditions to be in need of maintenance, repair or replacement.  
**RU** = Upgrades are systems and/or components that may not have been available or have been improved since the building was constructed. These may be, but are not limited to safety related items; such as GFCI receptacle and smoke detector locations and the installation of safety glass where subject to human impact.

## SITE & GROUNDS

### WALKWAYS

**SC** **s-21:** The gap between the walkway sections creates an uneven and/or unstable surface. This condition poses a trip hazard, especially for someone wearing heels. We recommend correcting the condition(s) noted for safety reasons.



## LANDSCAPE IRRIGATION

- CR** **s-25:** Testing of the landscape irrigation system is beyond the scope of this inspection. However, one or more of the sprinkler components leaks at the left rear of the building. We suggest that all leaking, malfunctioning or damaged sprinkler components should be repaired or replaced.



## ROOF

### JACK/VENT FLASHINGS

- CR** **s-44:** A jack/vent flashing on the left side of the roof is missing. This can allow leaks. We suggest a qualified roofer should replace all missing, improperly installed, damaged or deteriorated flashings.



Missing



Installed

### DOWNSPOUT CONDITIONS

- s-46:** Downspouts empty water into confined areas on several sides of the building. This can promote flooding or ponding. We suggest the downspouts should be rerouted to a better location or connected to subsurface drains.



## PLUMBING - PLUMBING FIXTURE CONDITIONS

### FAUCETS

- s-72:** The kitchen sink faucet is dripping. We suggest all dripping faucets should be repaired or replaced by a qualified plumber.

## WATER HEATER

### INSTALLATION

- s-83:** The remote control for the water heater is installed on the exterior. The control is subject to damage from exterior elements and this is contrary to manufacturers installations requirements. We suggest that a qualified plumber should install the remote an acceptable interior location.




## ELECTRICAL - FIXTURE CONDITIONS

### RECEPTACLES ALL AREAS


- s-103:** In the area(s) listed below receptacle(s) have an obstruction in one or more of the plug openings. We suggest the receptacle(s) should be repaired/replaced. A qualified technician should do the work.

Dining room



### SWITCHES ALL AREAS

**s-105:** In the area(s) listed below one or more dimmer light switches were hot at the time of this inspection. This suggests a defective device, or incompatibility between the ratings of the bulb(s) and the dimmer. This condition is a fire risk. We suggest a qualified electrician could replace the switch. Living room




117°

## ELECTRICAL - WIRING CONDITIONS

### BRANCH CIRCUITRY INTERIOR

**s-107:** In the area(s) listed below there is open junction box(es). Lack of covers on junction boxes is a shock or fire hazard. We DID NOT necessarily list all locations. We suggest a qualified electrician should check the system and install a proper cover on all junction boxes.


Crawlspace



## HEATING - FORCED AIR UNIT

### CONDITIONS: DUCTS & INSULATION


**s-117:** Joint(s) in the ductwork serving family room have come apart. This allows a significant leak of conditioned air. We suggest a qualified heating technician should repair the all disconnected ducts.



## GARAGE

### VEHICLE DOOR OPENER

**s-135:** The optical sensor or track beam installed on the garage door opener (which activates the reversing eye system) is installed at the incorrect height, more than 6 inches above the floor. This could allow small children or animals to move under the beam without activating the safety feature. This is a safety concern. We suggest the optical sensor or track beam should be installed six inches above the floor of the garage or in accordance with the manufacturer's specifications by a qualified garage door technician.




## BATHROOM

### Primary

### BIDET

**s-168:** The temperature for the bidet hot water is set too high. Excessively-high water temperature above 110 degrees F. can cause scalding injury. We suggest a qualified plumber should make corrections as necessary.



127°

### Guest

### SHOWER FIXTURES

**s-172:** The temperature of the tub/shower water does not get very hot on the high setting. We suggest a qualified plumber should evaluate the temperature control mixing valve and make repairs as necessary.




90°

## LAUNDRY AREA

### DRYER VENT

- s-177:** The dryer exterior vent cap is bent or damaged and can clog with lint, dirt or debris. This can be a fire hazard, and reduces dryer efficiency. We suggest the vent cap should be replaced.






Dear John Smith,

We have enclosed the following Full Report for the property inspection we conducted for you on Monday, July 4, 2022 at:

1234 Main Street  
Torrance, California 90505

Our report is designed to be clear, easy to understand, and helpful. Please take the time to review it carefully. If there is anything you would like us to explain, or if there is other information you would like, please feel free to call us. We would be happy to answer any questions you may have.

Throughout the report, you'll find special symbols at the front of certain comments. Below are the symbols and their meanings:


-  = Conditions in their present state may pose a hazard to humans, the structure or both. = Conditions that warrant further evaluation by a qualified specialist, disclosure from the sellers, or future observations.
-  = Conditions to be in need of maintenance, repair or replacement.
-  = Upgrades are systems and/or components that may not have been available or have been improved since the building was constructed. These may be, but are not limited to safety related items; such as GFCI receptacle and smoke detector locations and the installation of safety glass where subject to human impact.

We thank you for the opportunity to be of service to you.

Sincerely,



Steve Carroll



## Table of Contents

EXECUTIVE SUMMARY.....	2
INTRODUCTION.....	10



INSPECTION INFORMATION..... 11

SITE & GROUNDS..... 13

EXTERIOR..... 14

ROOF..... 15

STRUCTURE..... 17

PLUMBING..... 19

WATER HEATER..... 20

ELECTRICAL..... 21

HEATING..... 24

ATTIC..... 26

GARAGE..... 27

INTERIOR..... 28

KITCHEN..... 30

BATHROOM..... 31

LAUNDRY AREA..... 33

The Smith Report  
 1234 Main Street  
 Torrance, California 90505 Monday, July 4,  
 2022

## INTRODUCTION

We have inspected the major structural components and mechanical systems for signs of significant nonperformance, excessive or unusual wear and general state of repair. The inspection does not include any attempt to find or list cosmetic flaws. You, the client, are the final judge of aesthetic issues. Our inspection is conducted in accordance with the Standards of Practice of the California Real Estate Inspection Agreement. A copy of these standards are included with the Inspection Agreement and available at [www.creia.org](http://www.creia.org) . The following report is an overview of the conditions observed.

Any statements made in the body of the inspection report pertaining to left, right, front or rear are referenced as if the inspector is standing at the front of the building.

Other than new construction, we recommend having the locks on all of the exterior doors rekeyed after taking possession of the property for security reasons.

The presence of furnishings, personal items and decorations in occupied structures sometimes limits the scope of the inspection. For instance, the placement of furniture prevents access to every electrical receptacle. In the report, there may be specific references to areas and items that were inaccessible. We can make no representations regarding conditions that may be present but were concealed or inaccessible for review. With access and an opportunity for inspection, reportable conditions may be discovered. Inspection of the inaccessible areas will be performed upon arrangement and at additional cost after access is provided.

We do not review recall lists. Information regarding recalled appliances, fixtures and any other items in this property can be found on the Consumer Product Safety website. These items may be present but are not reviewed.

The presence or extent of building code or zoning violations is not the subject of this inspection nor is it included in this report. No information is offered on the legal use, or possible uses of the building or property. Information with regard to these issues may be available from the appropriate building and/or zoning agency. Important information about this property may be a matter of public record. However, a search of public records is not in the scope of this inspection. We recommend the buyer review all appropriate public records if this information is desired.

We recommend the buyer(s) ask the sellers to provide any and all owners manuals and warranties that they may have for the equipment installed at the property.

We also recommend asking the sellers for any permits and inspection records with finalized signatures for any changes or additions that may have been made to the structure, and/or any known conditions that may have been inadvertently left out of the disclosure statements.

This report is a "snapshot" of the property on the date of the inspection. The structure and all related components will continue to deteriorate/wear out with time and may not be in the same condition at the close of escrow.

Photographs and videos when used, are simply a tool to convey our findings as observed, they are not intended to enhance the findings or diminish those findings not photographed. Any deficiency discussed in this report should be carefully considered by the client and reviewed with the real estate agent as appropriate. Because a report of a deficiency is often based on the experience of the inspector using visual clues, it should be understood more extensive problems can be present which can be more costly to resolve than simply correcting the visible symptoms. Further, it is beyond the scope of this inspection

Page 10 of 33

Copyright© 2006-2022 Carroll Property Inspections Office 310-375-4703  
Inspector: Steve Carroll

The Smith Report  
1234 Main Street  
Torrance, California 90505  
Monday, July 4, 2022

to list every instance of similar deficiencies. The inspector's notation of any given deficiency should be interpreted such that additional similar defects may be present or more extensive. Any reported deficiency may require additional investigation to better determine the number of similar defects and related problems in order to make an informed decision. We suggest you consult with your inspector and/or agent to gain a comfort level about any defect(s) cited in this report. As needed, consult an appropriate contractor/technician who can provide a detailed list of deficiency locations, specifications and costs of repairs or recommended further evaluation PRIOR TO THE CLOSE OF THE TRANSACTION for purchases without an inspection contingency or DURING THE INSPECTION CONTINGENCY for all other purchases.

While we make an effort to identify existing as well as potential problems, it is not possible for anyone to predict future performance of all the systems and appliances in a building. We suggest budgeting annually for unforeseen repairs and/or the purchase of a comprehensive home warranty policy.

This report is not intended for use by anyone other than the client named herein. No other persons should rely upon the information in this report. Client agrees to indemnify, defend and hold inspector harmless from any third party claims arising out of client's unauthorized distribution of the inspection report.

By accepting this inspection report, you acknowledge that you have reviewed and are in agreement with all of the terms contained in the standard California Real Estate Inspection Agreement contract provided by the inspector who prepared this report.

We recommend that the buyer conduct a thorough pre-closing walkthrough inspection. \*The

## INSPECTION INFORMATION

This report is conducted and based on the California Real Estate Inspectors Association (CREIA) Standards of Practice, some areas have been expanded for ease of review, a copy of the standards is available at [www.creia.org](http://www.creia.org). This report is intended only as a general guide to help the client make their own evaluation of the overall condition of the structure, and is not intended to reflect the value of the premises, nor make any representations as to the advisability of its purchase. The report expresses the personal opinion of the inspector, based upon his visual impressions of the conditions that existed at the time of the inspection only. The inspection and report are not intended to be technically exhaustive, or to imply that every component was inspected, or that every possible defect was discovered. No disassembly of equipment, opening of walls, moving of furnishings, appliances or stored items, or excavation was performed. All components and conditions which by the nature of their location are concealed, camouflaged or difficult to inspect are excluded from this report.

### REPORT #

1: 070422

### PROPERTY ADDRESS

2: 1234 Main Street  
Torrance, California 90505

### INSPECTOR

3: Steve Carroll

Inspector: Steve Carroll

Page 11 of 33

Copyright© 2006-2022 Carroll Property Inspections Office 310-375-4703

The Smith Report  
1234 Main Street  
Torrance, California 90505  
Monday, July 4, 2022

### DATE & TIME

4: Monday, July 4, 2022 at 9:00 AM

### CLIENT(S) NAME

5: John Smith

### ATTENDEES

6: The following people were present during or at the end of the inspection: client(s) and selling agent.

### TYPE OF INSPECTION

7: This inspection and subsequent report was conducted on a single family residence.

8: At the time of the inspection the building was occupied and access to some items, such as; electrical outlets, windows, wall or floor surfaces and cabinets are or may be restricted by furniture or personal belongings. Any such items are excluded from this inspection.

### BUILDING AGE

9: The age of the building was reported to be 5 years old.

### WEATHER/SOIL

10: Weather conditions at the start of the inspection: the sky was clear, the outside temperature was between 70-80 degrees and the ground was dry.

## **PRIOR WEATHER**

**11:** No rain fell during the inspection, or in the preceding 24 to 48 hours.

## **ELECTRIC SHUT OFF LOCATION**

**12:** The electric panel and/or shut off location is on the right rear of the building.

## **WATER SHUT OFF LOCATION**

**13:** The water shut off valve is located on the front of the building.

## **GAS METER AND SHUT OFF**

**14:** The gas meter and/or shut off valve are located on the left side of the building.

## **ENVIRONMENTAL CONCERNS**

**15:** Environmental issues include but are not limited to asbestos, lead paint, lead contamination, radon, toxic waste, formaldehyde, toxic mold, electromagnetic radiation, buried fuel oil tanks, ground water contamination and soil contamination. We are not trained or licensed to recognize or discuss any of these materials. We may make reference to one or more of these materials in this report when we observe one of the common forms of these substances. If further study or analysis seems prudent, the advice and services of the appropriate specialists is recommended. Information related to these products can be found in the "Homeowners Guide to Earthquake Safety & Environmental Hazards" pamphlet.

Inspector: Steve Carroll

Page 12 of 33



**16:** Recent studies have shown that Americans spend up to 90 percent of their time at home. Indications from a growing body of scientific evidence suggest that the air within homes and other buildings can be more polluted than the outdoor air in even the largest and most industrialized cities. Thus for many people, the risks to health may be greater due to indoor rather than outdoor air pollution. For more information regarding indoor air quality we recommend reviewing, "The Inside Story" a guide to indoor air quality. Published by the Environmental Protection Agency, in conjunction with: The Consumer Product Safety Commission, Office of Radiation and Indoor Air. Or visit the website at: <http://www.epa.gov/iaq/pubs/insidest.html>

## **SITE & GROUNDS**

The items listed are visually observed to determine their current condition during the inspection, areas concealed from view by any means are excluded from this report. The permanently installed components or equipment are checked for basic operation, with exception to lawn sprinklers and low voltage yard lighting. This inspection is a visual observation and does not attempt to determine site drainage performance or the condition of any underground piping, including municipal water and sewer service piping or concealed cleanouts. This inspection is not intended to address or include any geological conditions or site stability information, for information in these areas we recommend consulting with a geologist and/or a geotechnical engineer.

## LIMITATIONS & EXCLUSIONS: IRRIGATION

**17:** Operation and evaluation of irrigation (sprinkler) systems is outside of the scope of this inspection and was not inspected. We suggest that you have the owner or a sprinkler technician demonstrate the irrigation system and any related equipment.

## DESCRIPTIONS: WALKWAYS

**18:** The walkway surface material is concrete.

## DESCRIPTIONS: DRIVEWAY

**19:** The driveway surface material is concrete.

## GRADING

**20:** The grading of the lot adequately drains surface water and roof runoff away from the building, other than any exceptions noted.

Inspector: Steve Carroll

Page 13 of 33

## WALKWAYS


The Smith Report

1234 Main Street

Torrance, California 90505 Monday, July 4, 2022

Copyright© 2006-2022 Carroll Property Inspections Office 310-375-4703

**21:** The gap between the walkway sections creates an uneven and/or unstable surface. This condition poses a trip hazard, especially for someone wearing heels. We recommend correcting the condition(s) noted for safety reasons.



## DRIVEWAY

**22:** The driveway is in acceptable condition.

## GATES

**23:** The gate(s) are in acceptable condition.


## WOOD FENCING

**24:** The wood fencing is in acceptable condition. Wood fences have a finite service life. Maintaining the bases of the fence posts free and clear of rotting leaves, and occasional treatment with a wood

preservative will slow deterioration, and prolong the effective life of wood fences and fence posts.

## LANDSCAPE IRRIGATION

**25:** Testing of the landscape irrigation system is beyond the scope of this inspection. However, one or more of the sprinkler components leaks at the left rear of the building. We suggest that all leaking, malfunctioning or damaged sprinkler components should be repaired or replaced.



## EXTERIOR

The exterior surfaces and materials of the structure are visually observed to determine their current condition. Moisture intrusion through cracks or openings in the exterior siding, trim, windows and doors are the source of moisture deterioration and damage. We recommend sealing all cracks or openings in, and between the exterior siding and trim materials, especially around windows and doors. Routine maintenance may extend the service life and minimize deterioration of the exterior surfaces. Areas hidden from view by vegetation and/or stored items can not be observed and are not included in this

Inspector: Steve Carroll

Page 14 of 33

Copyright© 2006-2022 Carroll Property Inspections Office 310-375-4703

The Smith Report  
1234 Main Street  
Torrance, California 90505  
Monday, July 4, 2022

inspection.

### DESCRIPTIONS: COVERINGS

**26:** The exterior wall covering is stucco.

### DESCRIPTIONS: WINDOWS

**27:** The exterior window material is vinyl.

### DESCRIPTIONS: TRIM

**28:** The predominant material used to trim the exterior features is wood.

### WOOD SIDING

**29:** The exterior wood siding is in acceptable condition. Periodic maintenance is recommended to extend the materials service life.

### WINDOWS GENERAL

**30:** The exterior portions of the windows are in adequate condition, other than any exceptions noted. We cannot report on hidden or inaccessible damage.

### DOORS GENERAL

**31:** The exterior doors are in adequate condition.

### FASCIA

**32:** The fascia (boards nailed across the ends of the rafters at the eaves) is in adequate condition, other than any exceptions noted. We do not physically "touch" the trim areas, and cannot report on hidden or inaccessible damage.

### **EAVES/SOFFITS**

**33:** The eaves and overhangs are in adequate condition, other than any exceptions noted. We do not physically "touch" the trim areas, and cannot report on hidden or inaccessible damage.

### **VEGETATION**

**34:** Bushes are overgrown around of the building. This can lead to moisture intrusion and pest infestation. We suggest the bushes should be pruned and or removed as part of routine maintenance.

### **BALCONY SURFACE**

**35:** The deck(s)/balcony(s) are finished with a coating that provides both the walking surface and the waterproof membrane. The coating is in adequate condition. These membranes are quite durable but still require periodic repair and recoating.

## **ROOF**

The visible portions of the roof and components are observed to determine their current condition during the inspection, areas concealed from view by any means are excluded from this report. The inspector cannot and does not offer an opinion or warranty as to whether the roof leaks or may be subject to future leakage. This report is issued in consideration of the foregoing disclaimer. The only way to determine whether a roof is absolutely water tight is to observe it during a prolonged rainfall which is beyond the scope of this report. The testing of gutters, downspouts and underground drain piping is beyond the

Inspector: Steve Carroll

Page 15 of 33

Copyright© 2006-2022 Carroll Property Inspections Office 310-375-4703

The Smith Report  
1234 Main Street  
Torrance, California 90505  
Monday, July 4, 2022

scope of this report.

### **DESCRIPTIONS: INSPECTION METHOD**

**36:** The accessible, visible areas of the roof were inspected by walking on the roof.

### **DESCRIPTIONS: MATERIALS**

**37:** The material in the roof covering, or its type, is asphalt-composition shingles.

### **DESCRIPTIONS: SLOPE**

**38:** The slope or pitch of the roof is medium.

### **DESCRIPTIONS: PENETRATIONS**

**39:** The connections and penetrations in the roofing surface are sealed with sheet metal and mastic.

### **DESCRIPTIONS: VALLEYS**

**40:** The valleys are flashed with sheet metal.

### **DESCRIPTIONS: ROOF DRAINAGE**

**41:** The roof drainage system is comprised of gutters and downspouts.

### **COMPOSITION SHINGLES**


**42:** The asphalt composite shingle surface on this building is in adequate condition.

### FLASHINGS OVERALL

**43:** The mastic used as a sealant at the connections between roofing material and other features will likely deteriorate before the rest of the roof. We suggest periodic examination and maintenance of these joints and/or connections is suggested to prevent future leaks.

### JACK/VENT FLASHINGS

**44:** A jack/vent flashing on the left side of the roof is missing. This can allow leaks. We suggest a qualified roofer should replace all missing, improperly installed, damaged or deteriorated flashings.



Missing Installed

### GUTTER CONDITIONS

**45:** The gutters are in adequate condition. Regular maintenance is suggested.


Page 16 of 33

### DOWNSPOUT CONDITIONS

The Smith Report  
1234 Main Street  
Torrance, California 90505 Monday, July 4, 2022

Copyright© 2006-2022 Carroll Property Inspections Office 310-375-4703  
Inspector: Steve Carroll

**46:** Downspouts empty water into confined areas on several sides of the building. This can promote flooding or ponding. We suggest the downspouts should be rerouted to a better location or connected to subsurface drains.



## STRUCTURE

Sections of the foundation and/or structural components of the building are inaccessible because they are installed at or below grade level, and/or behind walls. Assessing the structural integrity of a building is beyond the scope of a home inspection. The inspector's visual observations take into account the age of the building and the construction standards of that time, older structures may lack many of the modern framing and seismic connections presently being utilized. Foundations may have curing cracks that do



not represent a structural problem. All concrete experiences some degree of cracking due to shrinkage in the drying process. If large cracks are present along with movement, we recommend further evaluation by a structural engineer, foundation specialist, geologist or a geotechnical engineer. All exterior grades should allow for surface and roof water to be diverted away from the foundation system.

## DESCRIPTIONS

### FOUNDATION

**47:** The foundation material and design is concrete perimeter wall with interior stem walls.

### CRAWLSPACE ACCESS

**48:** The underbuilding crawl space was entered and inspected from an access hatch or door on the right side of the exterior.

### CRAWLSPACE VENTILATION

**49:** The foundation is ventilated by screened foundation vents.

### FLOOR SYSTEMS

**50:** The floor system consists of wood joists.

### FLOOR INSULATION

**51:** The thermal insulation visible in the crawlspace is batts.

### WALL SYSTEMS

**52:** The load bearing walls are conventional wood stud construction.

Inspector: Steve Carroll

Page 17 of 33

Copyright© 2006-2022 Carroll Property Inspections Office 310-375-4703

The Smith Report  
1234 Main Street  
Torrance, California 90505  
Monday, July 4, 2022

### CEILING SYSTEMS

**53:** The ceiling system consists of wood joists.

### ROOF SYSTEMS

**54:** The roof structure covering this building is a conventional rafter system.

## FOUNDATION & SEISMIC CONDITIONS

### RAISED FOUNDATION

**55:** The foundation and other visible elements of the support structure are in adequate condition, given the age of the structure, and other than any exceptions noted. No critical sags, cracks, or deterioration are visible.

### ANCHOR BOLTS & STRAPS

**56:** Anchor bolts are installed. The visible anchors are in acceptable condition.

### CRIPPLE WALLS

**57:** Due to the configuration and framing of this building there are no cripple walls.

## VENTILATION & MOISTURE CONDITIONS

### CRAWLSPACE VENTILATION

**58:** Ventilation of the crawl space is adequate, other than any exceptions noted.

### **CRAWLSPACE MOISTURE**

**59:** The soil in the crawl space was dry at the time of this inspection. No adverse conditions or damage related to excessive moisture was observed, other than any exceptions noted.

## **FLOOR & WALL CONDITIONS**

### **FLOOR JOISTS**

**60:** In the areas where the floor framing is visible, all components are in adequate condition, other than exceptions noted.

### **INSULATION**

**61:** Some of the insulation batts are missing or have fallen out of place. We suggest that where insulation is missing, new insulation should be installed. Where insulation is out of place, it should be put back into place. A qualified contractor could do the work.

## **ROOF STRUCTURE CONDITIONS**

### **CEILING JOISTS**

**62:** The ceiling joists are in adequate condition, other than any exceptions noted. Ceiling joists are the structural members that support the finished ceiling below.

### **RAFTERS**

**63:** The roof structure is constructed in a manner typical of buildings of this type and age. The rafters, the boards that support the roof sheathing, are in adequate condition, other than any exceptions noted.

The Smith Report  
1234 Main Street  
Torrance, California 90505 Monday, July 4, 2022

## **STRUCTURE OVERALL GENERAL COMMENTS**

**64:** After examination of the visible and readily accessible portions of the structure, we conclude that it is in adequate condition for its age, other than any exceptions noted.

## **PLUMBING**

Our inspection of the plumbing system includes a visual examination of the exposed portions of the domestic water supply lines, water heater, drain, waste and vent lines, gas lines, faucets, fixtures, valves, drains, traps, exposed pipes and fittings. These items are examined for excessive or unusual wear, leakage, and general state of repair. The hidden nature of piping prevents inspection of every pipe and joint. Plumbing leaks can be present but not evident in the course of a normal inspection. A sewer lateral test to determine the condition of the underground sewer lines is beyond the scope of this inspection. If desired, a qualified individual could be retained for such a test. Our review of the plumbing system does not include landscape irrigation systems, water wells, on site and/or private water supply systems, water

quality, off site community water supply systems or private (septic) waste disposal systems. If desired, review of such systems should be performed by qualified specialists prior to the close of escrow.

## DESCRIPTIONS

### INTERIOR SUPPLY PIPING

**65:** Where visible, the water supply piping inside the structure used to deliver water to the fixtures is copper.

### GAS SUPPLY PIPING

**66:** Where visible, the gas supply piping inside the structure used to deliver gas is steel pipe.

### DRAIN, WASTE & VENT

**67:** The visible drain, waste and vent (DWV, the "sewer pipe") piping within the structure is ABS plastic.

## SUPPLY CONDITIONS

### INTERIOR WATER PIPES

**68:** The accessible supply piping is in adequate condition, other than any exceptions noted.

### WATER PRESSURE

**69:** The water pressure, as measured from the exterior of the building, is in the high range of normal water pressure.

### WATER FLOW

**70:** All accessible plumbing fixtures were operated during the inspection, and reasonable water flow was confirmed when other fixtures were operated simultaneously. The system appears satisfactory, other than any exceptions noted.

## DRAIN, WASTE & VENT CONDITIONS

### DRAIN & WASTE LINES

**71:** The visible drain and waste piping is in adequate condition, other than any exceptions noted.

Inspector: Steve Carroll

Page 19 of 33

Copyright© 2006-2022 Carroll Property Inspections Office 310-375-4703

The Smith Report  
1234 Main Street  
Torrance, California 90505  
Monday, July 4, 2022

## PLUMBING FIXTURE CONDITIONS

### FAUCETS



**72:** The kitchen sink faucet is dripping. We suggest all dripping faucets should be repaired or replaced by a qualified plumber.

## FUEL GAS CONDITIONS

### GAS METER & SHUTOFF

**73:** An automatic seismic shut off valve is installed at the gas meter as a safety feature. Testing of the shut off valve is beyond the scope of this inspection.

## WATER HEATER

**DESCRIPTIONS: LOCATION**

74: The water heater is mounted on the right side of the exterior.

**DESCRIPTIONS: AGE**

75: The age of the water heater is estimated to be five years.

**DESCRIPTIONS: CAPACITY OF THE WATER HEATER**

76: The capacity of the "tankless" water heater is rated at a first hour recovery of 203 gallons and a maximum flow rate of 4.9 gallons per minute.

**DESCRIPTIONS: ENERGY SOURCE**

77: The energy source for the water heater is natural gas.

**CONNECTIONS & VALVES**

78: The water heater piping and valve installation is acceptable, other than any exceptions noted.

**T&P VALVE**

79: The water heater is equipped with a T&P (temperature and pressure) relief valve with a discharge pipe that terminates away from the water heater at an appropriate location, other than any exceptions noted.

**GAS VALVES**

80: The gas supply piping installation includes a hand operated 90-degree shutoff valve in the vicinity of the appliance. Operation of the valve is not within the scope of this inspection.

**VENTS**

81: The water heater vents are in adequate condition, other than any exceptions noted.

**COMBUSTION AIR**



82: The combustion air supply for the water heater is adequate, other than any exceptions noted.

**INSTALLATION**

The Smith Report  
1234 Main Street  
Torrance, California 90505  
Monday, July 4, 2022



83: The remote control for the water heater is installed on the exterior. The control is subject to damage from exterior elements and this is contrary to manufacturers installations requirements. We suggest that a qualified plumber should install the remote an acceptable interior location.



## GENERAL

**84:** The water heater is a newer model, and is operating satisfactorily.

**85:** Most 'on demand' water heater manufactures require annual maintenance of the unit. Inquires should be made to the sellers at to the service history of this unit. We suggest review of the product manual and have the unit serviced as necessary by a qualified plumber.

## ELECTRICAL

Our examination of the electrical system includes a visual examination of the exposed and accessible service entry wiring, service panels, subpanels, overcurrent protection devices, branch circuit wiring, light fixtures, switches and receptacles. Service equipment, proper wiring methods, grounding, bonding and overcurrent protection are focal points. We inspected for adverse conditions such as improper installation of aluminum wiring, lack of grounding and bonding, overfusing, exposed wiring, open-air wire splices, reversed polarity and defective GFCIs. The hidden nature of the electrical wiring prevents inspection of every length of wire. Performing voltage tests, load calculations or determining the adequacy of the electrical system is outside the scope of this inspection. Telephone, video, audio, data transfer, security system, intercom, landscape lighting, and other low voltage wiring was not included in this inspection unless specifically noted. We recommend you have the seller or a qualified specialist demonstrate the serviceability of such systems to you.

## LIMITATIONS & EXCLUSIONS

### LIMITATIONS & EXCLUSIONS

**86:** Determining if various electrical circuits will support the use of high load appliances such as hair dryers, toasters, microwave ovens, space heaters, etc., and testing the overcurrent protective protection to see if they 'trip' is beyond the scope of this inspection.

## DESCRIPTIONS

### SERVICE ENTRY

**87:** The service entrance supplying electricity into the building is an overhead service drop.

Inspector: Steve Carroll

Page 21 of 33

### AMPS & VOLTS

**88:** The voltages available at the building are both 120 and 240.

The service ampacity is 200 amps.

Determination of service capacity was based upon the labeled rating of the main electrical service disconnect.

### CONDUCTORS

**89:** The branch circuit conductor wire material is copper, exclusively.

### WIRING TYPE

**90:** The wiring used in this structure is non-metallic sheathed cable "Romex".

## **GROUNDING**

**91:** The electrical system is grounded to a driven rod and water supply piping.

## **CIRCUIT PROTECTION**

**92:** Branch circuit overload protection is provided by circuit breakers.

## **SUBPANELS**

**93:** A subpanel is located in the laundry.

## **ELECTRICAL SYSTEM CONDITIONS**

### **SERVICE CAPACITY**

**94:** The size of the service capacity is normal for a building of this size and age and appears to be adequate for the existing demand.

### **SERVICE DROP**

**95:** The service drop is in adequate condition, other than any exceptions noted.

### **SERVICE GROUNDING & BONDING**

**96:** The visible system and equipment grounding are acceptable, other than any exceptions noted.

## **MAIN PANEL CONDITION**

### **MAIN DISCONNECT**

**97:** The main electrical disconnect mechanism appears to be in adequate condition, other than any exceptions noted. To avoid disrupting power to the building, we did not operate the switch(es).

### **ENCLOSURE**

**98:** The main service panel and interior components are in adequate condition, other than any exceptions noted.

### **CIRCUIT BREAKERS**

**99:** Circuits in the main panel are labeled. We did not verify the accuracy of the labeling. We suggest checking the labeling by operating the breakers and observing what equipment or room is controlled by each breaker.

The Smith Report  
1234 Main Street  
Torrance, California 90505  
Monday, July 4, 2022

## **AFCI BREAKERS**

**100:** Arc Fault Circuit Interrupter (AFCI) protection is provided by special circuit breaker(s) installed in the panel to protect all of the outlets on the circuit served by this breaker(s). We suggest testing the device monthly using the built-in test button.

## **SUBPANEL CONDITIONS**

### **ENCLOSURE**

**101:** The subpanel and interior components are in adequate condition, other than any exceptions noted.


### **CIRCUIT BREAKERS**

- 102:** Some circuits in the subpanel are labeled, some are not. We did not verify the accuracy of the labeling. We suggest checking the labeling by operating the breakers and observing what equipment or room is controlled by each breaker. All of the circuits should be labeled.

### **FIXTURE CONDITIONS**

#### **RECEPTACLES ALL AREAS**

- 103:** In the area(s) listed below receptacle(s) have an obstruction in one or more of the plug openings. We suggest the receptacle(s) should be repaired/replaced. A qualified technician should do the work.  
Dining room



#### **GFCI'S ALL AREAS**

- 104:** GFCI (ground fault circuit interrupter) protection is present and function when tested. We suggest testing the devices monthly using the built in test buttons.


Inspector: Steve Carroll  
Page 23 of 33

#### **SWITCHES ALL AREAS**

The Smith Report  
1234 Main Street  
Torrance, California 90505 Monday, July 4, 2022



- 105:** In the area(s) listed below one or more dimmer light switches were hot at the time of this inspection. This suggests a defective device, or incompatibility between the ratings of the bulb(s) and the dimmer. This condition is a fire risk. We suggest a qualified electrician could replace the switch. Living room



117°

## LIGHTS ALL AREAS


**106:** The light fixtures in this building are generally in adequate condition, other than any exceptions noted.

## WIRING CONDITIONS

### BRANCH CIRCUITRY INTERIOR

**107:** In the area(s) listed below there is open junction box(es). Lack of covers on junction boxes is a shock or fire hazard. We DID NOT necessarily list all locations. We suggest a qualified electrician should check the system and install a proper cover on all junction boxes.

Crawlspace



## HEATING

Our examination of the heating system includes a visual examination of the exposed and accessible equipment, thermostat, safety controls, venting and the means of distribution. These items are examined for excessive or unusual wear and general state of repair. Our inspection of a heating system includes activating it via the thermostat and checking for appropriate temperature response. Modern furnace heat exchangers are inaccessible by design, which would require significant dismantling of the furnace to be evaluated. Our inspection does not include disassembly of the furnace, therefore heat exchangers are not included in the scope of this inspection. To obtain maximum efficiency and reliability from your heating system, we recommend annual seasonal servicing and inspection by a qualified technician.

Inspector: Steve Carroll

Page 24 of 33

## FORCED AIR UNIT

### DESCRIPTIONS: TYPE & FUEL

**108:** The heating system is gas forced air furnace. Forced air furnaces operate by heating a stream of air which is moved by a blower through a system of ducts. Important elements of the system include the heat



exchanger, exhaust venting, blower, controls, and ducting. Average life of a gas furnace is 15-20 years.

**DESCRIPTIONS: APPROX. AGE**

**109:** The age of the heating plant, based on the manufacturer's data plate is 5 years old.

**DESCRIPTIONS: LOCATION**

**110:** The heating system is located in the attic.

**DESCRIPTIONS: BTU(S)**

**111:** The input rating of the heating plant is 100,000 BTU's

**DESCRIPTIONS: FILTER**

**112:** The filter type in this system is a disposable device.

**CONDITIONS: FORCED AIR UNIT**

**113:** The inducer fan is in operating condition, other than any exceptions noted.

**CONDITIONS: FILTERS**

**114:** The filter is dirty. This decreases its effectiveness, and blocks airflow. This can dramatically decrease the efficiency of both the heating and cooling system if present. We suggest changing or washing the filters now, and at regular intervals thereafter. The filter should be replaced with a properly sized filter to ensure proper function. If the system has been operating in this condition for an extended period of time, service by a licensed HVAC contractor is advised to check the cleanliness of the fan, evaporator coil, ducts, etc., and clean it as needed.

**CONDITIONS: RETURN AIR**

**115:** The return air for the heating system installation is functional, other than any exceptions noted.

**CONDITIONS: BLOWER & AIR HANDLER**

**116:** The blower was functioning at the time of inspection, other than any exceptions noted. Regular routine maintenance is suggested to keep the blower functioning as designed.

Inspector: Steve Carroll

Page 25 of 33

**CONDITIONS: DUCTS & INSULATION**

**117:** Joint(s) in the ductwork serving family room have come apart. This allows a significant leak of conditioned air. We suggest a qualified heating technician should repair the all disconnected ducts.



#### **CONDITIONS: THERMOSTAT**

**118:** The unit responded to the user controls on the thermostat. Keep in mind that the thermostat is a programmable device with many options for setback settings, timed events, etc. We made no attempt to test all of the functions of this thermostat.

#### **CONDITIONS: GAS VALVES**

**119:** The gas supply piping installation includes a hand operated 90-degree shutoff valve in the vicinity of the appliance. Operation of the valve is not within the scope of this inspection.

#### **CONDITIONS: VENTING**

**120:** The visible components of the furnace venting system appears to be in acceptable condition, other than any exceptions noted.

#### **CONDITIONS: COMBUSTION AIR**

**121:** The combustion air supply is adequate, other than any exceptions noted.

#### **CONDITIONS: BURNERS**

**122:** The burners were inspected and are functional, other than any exceptions noted.

#### **CONDITIONS: IGNITION SYSTEM**

**123:** The burner is equipped with a hot surface ignition system, which is an energy saving feature that allows operation without the need for a continuously burning pilot light. The ignition system was activated during the inspection and is in adequate condition, other than any exceptions noted.

#### **CONDITIONS: GENERAL CONDITIONS**

**124:** The heating system is relatively new, responds to normal operating controls, and with routine maintenance, should be reliable for a number of years.

## **ATTIC**

Our inspection of the accessible areas of the attic includes a visual examination of the roof framing (see also Structure Section), ventilation, insulation, and any plumbing, electrical and mechanical systems therein. There are often heating ducts, bathroom vent ducts, electrical wiring, chimneys and appliance and plumbing vents in the attic, some of which may not be accessible. We examine the visible systems and components for excessive or unusual wear and general state of repair. When low clearance, framing

Inspector: Steve Carroll

Page 26 of 33

design or obstructions, deep insulation and mechanical components prohibit walking safely in an unfinished attic, inspection is conducted from the available service platforms or access openings only.

**DESCRIPTIONS: ACCESS**

**125:** The attic is accessible at the ceiling hatch in the primary bedroom closet.

**DESCRIPTIONS: INSULATION**

**126:** The thermal insulation visible in the attic is batts.

**DESCRIPTIONS: VENTILATION**

**127:** The attic space is ventilated by soffit and gable vents.

**ACCESS**

**128:** The attic access is acceptable for normal entry, other than any exceptions noted.

**INSULATION**

**129:** The insulation visible in the accessible areas of the attic is in acceptable condition, other than any exceptions noted, and consistent with the age of the structure.

**ATTIC VENTILATION**

**130:** The attic is adequately vented, consistent with industry standards, other than any exceptions noted.

## GARAGE

Our inspection of the garage includes a visual examination of the readily accessible portions of the walls, ceilings, floors, vehicle and personnel doors, steps and stairways, fire resistive barriers, garage door openers and hardware if applicable. Garage door openers are operated with the mounted control button only. Please note that a representative sample of accessible windows and electrical receptacles are inspected. These features are examined for proper function, excessive wear and general state of repair. In some cases, all or portions of these components may not be visible because of stored personal property. In such cases, some items may not be inspected.

**DESCRIPTIONS: VEHICLE PARKING**

**131:** The vehicle parking area for this building is an attached garage.

**DESCRIPTIONS: GARAGE DOOR**

**132:** The garage is equipped with a roll up type door.

**DESCRIPTIONS: DOOR OPENER**

**133:** The garage door is controlled by an automatic opener.

Inspector: Steve Carroll

Page 27 of 33

**VEHICLE DOOR OPENER**

The Smith Report


1234 Main Street

Torrance, California 90505 Monday, July 4, 2022

**134:** The garage door opener(s) operated properly to raise and lower the door, other than any exceptions noted, including the auto-reverse mechanism, which stopped and reversed the direction of the door when striking an object in its path. We recommend regular lubrication of the garage door tracks, rollers, springs

and mounting hardware. Sometimes the automatic self-closing mechanism on a garage door opener gets out of adjustment, and the reversing mechanism will not function as designed. The reversing mechanism is an important safety feature. We recommend monthly testing of the automatic reversing mechanism, per manufacturers specifications and UL standards. The optical sensor, if present, should also be tested. The door, opener, and related parts should be tested frequently, and repaired as necessary. The control switch for the opener(s) should also be mounted out of reach of small children.

**135:** The optical sensor or track beam installed on the garage door opener (which activates the reversing eye system) is installed at the incorrect height, more than 6 inches above the floor. This could allow small children or animals to move under the beam without activating the safety feature. This is a safety concern. We suggest the optical sensor or track beam should be installed six inches above the floor of the garage or in accordance with the manufacturer's specifications by a qualified garage door technician.



#### **VEHICLE DOOR & FRAME**

**136:** The garage door was operated and is in adequate condition, other than any exceptions noted.

#### **FIRE SEPARATION**

**137:** The wall and/or ceiling between the garage and the living space is of fire resistive construction as required by modern building standards. The fire separation system is acceptable, other than any exceptions noted.

#### **PASSAGE DOOR**

**138:** The door between the garage and the living space is of fire resistant construction. An automatic closer is installed. This is a useful feature, which provides a greater margin of safety.

#### **GARAGE FLOOR**

**139:** Minor cracking is evident in the floor slab, but there is no noticeable vertical displacement.

## **INTERIOR**

Our inspection of the interior includes a visual examination for structural and safety deficiencies of the readily accessible portions of the walls, ceilings, floors, doors, windows, cabinetry, countertops, steps, stairways, balconies, railings and smoke/carbon monoxide alarms. Not included in the scope of inspection are cosmetic conditions of floor and wall covering or determination of failed seals in insulated windows

Inspector: Steve Carroll

Page 28 of 33

and doors. Please note that a representative sample of accessible windows and electrical receptacles and fixtures are inspected. These features are examined for proper function, excessive wear and general state of repair. In some cases, all or portions of these components may not be accessible in an occupied building because of furniture and personal effects. In such cases these items are not inspected.

## DESCRIPTIONS

### WALLS & CEILINGS

**140:** The finished walls & ceilings inside this building are predominantly drywall.

### WINDOW TYPES

**141:** The predominant type, or design, of the operable windows in this structure is

casement. **FLOOR WALL & CEILING CONDITIONS**

### WALLS & CEILINGS

**142:** The basic structure surfaces of the interior walls, floors, and ceilings are in adequate condition, other than any exceptions noted.

## WINDOW CONDITIONS

### WINDOWS OVERALL

**143:** All of the windows were tested, and are functional, other than any exceptions noted.

### SAFETY GLASS

**144:** Safety glass is present in all locations where such glass was required at the time the building was constructed.

## DOOR CONDITIONS

### DOORS OVERALL

**145:** The interior doors are in adequate condition, other than any exceptions

noted. **STAIRWAY & RAILING CONDITIONS**

### STAIRWAYS

**146:** We used the stairs several times during the inspection. No specific deficiencies were noted at the time of this inspection, other than any exceptions noted.

### HANDRAILS

**147:** The stairway handrails are installed and in adequate condition, other than any exceptions

noted. **SMOKE & CARBON MONOXIDE ALARMS**

### SMOKE DETECTORS

**148:** The smoke alarm(s) are appropriately located. The smoke alarms(s) were inspected for location only. For future reference, testing with only the built-in test button verifies proper battery and horn function, but does not test the smoke sensor. We advise testing with simulated smoke upon occupying the building.

Inspector: Steve Carroll

Page 29 of 33

### CARBON MONOXIDE DETECTORS

**149:** Carbon monoxide alarms are installed. The carbon monoxide alarms were inspected for location

only. For future reference, testing with only the built-in test button verifies proper battery and horn function, but does not test the carbon monoxide sensor. Testing of the carbon monoxide alarms is beyond the scope of this inspection.

## KITCHEN

Our inspection of the kitchen includes a visual examination of the readily accessible portions of the appliances, floors, walls, ceilings, cabinets, and countertops. The kitchen was inspected for proper function of components, active plumbing leaks, excessive or unusual wear and general state of repair. We tested basic, major built-in appliances using normal operating controls. Where they are present, this included the dishwasher, garbage disposal, venting system, microwave and checking the burners or heating elements in the stove and oven. Accuracy and/or function of clocks, timers, temperature controls and self cleaning functions on ovens is beyond the scope of our testing procedure. Refrigerators or other appliances were not tested or inspected unless specifically noted.

### DESCRIPTIONS: COOKING FUEL

**150:** The heat source used for cooking is natural gas & electricity.

### DESCRIPTIONS: VENTILATION

**151:** Kitchen ventilation is provided by a hood over the cooking surface designed to exhaust to the exterior.

### CABINETS

**152:** The cabinets were in acceptable condition at the time of this inspection, other than any exceptions noted.

### APPLIANCES GENERAL

**153:** The built-in kitchen appliances were all tested by activating one of the user control functions. We did not test every function or cycle on each appliance and cannot confirm that every function or cycle is operable. Testing all cycles/functions on each appliance is recommended prior to close of escrow. Obtain a reputable Home Warranty Protection program to insure against future failure of any appliance that may occur after taking possession of the home.

### VENT SYSTEM

**154:** We tested the kitchen vent system. It is functional, other than any exceptions noted.

### RANGE

**155:** The range was operated with the normal operating controls. It is functional, other than any exceptions noted.

### OVEN

**156:** The oven was activated with the normal operating controls. It is functional, other than any exceptions noted.

### DISPOSAL

**157:** The disposal was turned on with normal user controls. It is functional, other than any exceptions noted.

**158:** The dishwasher responded to normal user controls and is functional, other than any exceptions noted.

### **DISHWASHER DISCHARGE**

**159:** The dishwasher drain is equipped with an air-gap fitting (the cylinder protruding above the sink). This ensures separation of the supply water from the waste water.

### **MICROWAVE**

**160:** The microwave oven was checked using the normal operating controls. It is functional, other than any exceptions noted.

## **BATHROOM**

Our inspection of the bathrooms includes a visual examination of the readily accessible portions of the plumbing fixtures, floors, walls ceilings, cabinets, and countertops. Bathrooms are inspected for active leaks, water damage, deterioration to floors and walls, proper function of components, excessive or unusual wear and general state of repair. Bathroom fixtures are run simultaneously to check for adequate water pressure and volume. Fixtures are tested using normal operating features and controls. Vent fans are tested and their ductwork examined where visible. Unusual bath features like steam generators or saunas are not inspected unless specifically discussed in this report.

### **Primary**

#### **VENTILATION**

**161:** We tested the bathroom exhaust fan. It is functional, other than any exceptions noted.

#### **SHOWER & TUB WALLS**

**162:** The shower wall material is in adequate condition, with any exceptions noted. The shower wall(s) will remain acceptable only as long as the joints are watertight. We suggest the joints should be kept properly caulked as part of routine maintenance.

#### **SHOWER ENCLOSURE**

**163:** The shower enclosure glass is safety labeled and in adequate condition, other than any exceptions noted.

#### **SHOWER FIXTURES**

**164:** The shower fixtures are functional, other than any exceptions noted. Routine maintenance should keep them functional and maximize their useful life.

#### **BATHTUB FAUCET & DRAINS**

**165:** The bathtub fixtures are functional, other than any exceptions noted. Routine maintenance should keep them functional and maximize their useful life.

#### **WASH BASIN & DRAINS**

**166:** The wash basins are in adequate condition, other than any exceptions noted.

#### **TOILETS**

**167:** The toilet is functional, other than any exceptions noted.

Inspector: Steve Carroll

Page 31 of 33

## BIDET

**168:** The temperature for the bidet hot water is set too high. Excessively-high water temperature above 110 degrees F. can cause scalding injury. We suggest a qualified plumber should make corrections as necessary.



127°

## Guest

### VENTILATION

**169:** We tested the bathroom exhaust fan. It is functional, other than any exceptions noted.

### SHOWER & TUB WALLS


**170:** The tub/shower grout and caulk is cracked, deteriorated and/or missing. Water leakage through unsealed areas can cause structural damage. Damage caused by water seepage cannot be determined by this visual inspection. We suggest all cracked or missing grout and caulking should be replaced to prevent moisture intrusion of the wall.

### SHOWER ENCLOSURE

**171:** The tub/showers are equipped with shower curtains. Care should be exercised to prevent overspray which can cause moisture related damage to the floor coverings and surrounding surfaces. We suggest consideration should be given to the installation of a permanent shower enclosure.

### SHOWER FIXTURES

**172:** The temperature of the tub/shower water does not get very hot on the high setting. We suggest a qualified plumber should evaluate the temperature control mixing valve and make repairs as necessary.



90°

### BATHTUB FAUCET & DRAINS

**173:** The bathtub fixtures are functional, other than any exceptions noted. Routine maintenance should keep them functional and maximize their useful life.

Inspector: Steve Carroll

Page 32 of 33



## WASH BASIN & DRAINS

**174:** The wash basin is in adequate condition, other than any exceptions noted.

## TOILETS

**175:** The toilet is functional, other than any exceptions noted.

# LAUNDRY AREA

Testing of clothes washers, dryers, water valves and drains are not within the scope of this inspection. We inspect the general condition and accessibility of the visible water supply, drain and electric and/or gas connections and dryer vent. If present, laundry sink features will be inspected.

## DESCRIPTIONS: DRYER

**176:** The clothes dryer is served only by a gas connection for the heating method. There is no 240-volt electric connection.

## DRYER VENT

**177:** The dryer exterior vent cap is bent or damaged and can clog with lint, dirt or debris. This can be a fire hazard, and reduces dryer efficiency. We suggest the vent cap should be replaced.



## ROOM VENTILATION

**178:** We tested the laundry area exhaust fan. It is functional, other than any exceptions noted.

## WASHER

**179:** There is no clothes washer overflow pan. Because of the location of this laundry area over wood flooring or finished space on the floor below, a pan connected to a drain is advised. We recommend installation of a drained catch pan under the washing machine, as an upgrade and preventive measure.

## GENERAL

**180:** The hookups for both the clothes washer and clothes dryer are in adequate condition, other than any exceptions noted. The appliances themselves were not tested, and are not within the scope of this inspection.

Copyright© 2006-2022 Carroll Property Inspections Office 310-375-4703

Inspector: Steve Carroll

Page 33 of 33